





order no.	L	L1	H	H1	X	Y
2611WN(F,P,S)	300	31	183	8	80	100
2612WN(F,P,S)	300	31	183	8	80	100
2613WN(F,P,S)	325	39	197	2	90	110
2614WN(F,P,S)	325	39	197	2	90	110
2611WN(F,P,S)/60	300	31	183	8	80	100
2612WN(F,P,S)/60	300	31	183	8	80	100
2613WN(F,P,S)/60	325	39	197	2	90	110
2614WN(F,P,S)/60	325	39	197	2	90	110



order no.	L	L1	H	H1	X	Y
2611WE(F,P,S)	315	33	186	8	80	100
2612WE(F,P,S)	315	33	186	8	80	100
2613WE(F,P,S)	340	39	197	2	90	110
2614WE(F,P,S)	340	39	197	2	90	110
2611WE(F,P,S)/60	315	33	186	8	80	100
2612WE(F,P,S)/60	315	33	186	8	80	100
2613WE(F,P,S)/60	340	39	197	2	90	110
2614WE(F,P,S)/60	340	39	197	2	90	110